

BASIC SETTINGS

The following basic settings are suitable for the majority of textiles.



160°C



Time 15 seconds



Pressure* 2-6 bar



Plastic carrier removal Hot/Cold peel

*The standard setting for a small base plate is 2-3 bar, with 4-6 bar for a large base plate. When using a heat press from a manufacturer other than Hot Screen, the pressure should be set to 0.5-1.5 kg/cm2.



